



BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	A
ROOF SQ FT	10,000

ROOF CONSTRUCTION										
ROOF AGE	1997	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input type="checkbox"/>	ISO	<input checked="" type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input checked="" type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input type="checkbox"/>	SCUPPERS	<input checked="" type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS								#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>					RATING	3
	RESEAL SEAMS	<input type="checkbox"/>		RIDGING/BLISTERS	<input type="checkbox"/>		SS RATING	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>		DECK REPAIR NEEDED	<input type="checkbox"/>			
	DECK REPAIR SUSPECTED	<input type="checkbox"/>		RESEAL/RPLACE FASTENERS	<input type="checkbox"/>			
	CRAZE CRACKING	<input checked="" type="checkbox"/>		VERY BRITTLE MEMBRANE	<input checked="" type="checkbox"/>			
	EXCESSIVE WEAR	<input checked="" type="checkbox"/>		MEMBRANE FIBERS EXPOSED	<input checked="" type="checkbox"/>			
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>					RATING	6
	FILL PONDING AREAS	<input type="checkbox"/>		FIX DECK DEFLECTION	<input type="checkbox"/>			
	SOME PONDING	<input checked="" type="checkbox"/>		EXCESSIVE PONDING	<input type="checkbox"/>			
		<input type="checkbox"/>			<input type="checkbox"/>			
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>					RATING	3
	RESEAL/REPAIR ALL	<input type="checkbox"/>		RESEAL/REPAIR SELECT	<input type="checkbox"/>		SS RATING	
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>		RESEAL/RECOAT WALL	<input type="checkbox"/>			
	RESEAL WALL FLASHING	<input type="checkbox"/>		COUNTERFLASH NEEDED	<input type="checkbox"/>			
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>					RATING	6
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>		ADD/ENHANCE OVERFLOW	<input type="checkbox"/>			
	CLEAR DRAINS	<input type="checkbox"/>		ADD GUTTER	<input type="checkbox"/>			
	GUTTER REPAIR NEEDED	<input type="checkbox"/>		GUTTER COATING NEEDED	<input type="checkbox"/>			
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>					RATING	6
	RESEAL/REPAIR ALL	<input type="checkbox"/>		RESEAL/REPAIR SELECT	<input type="checkbox"/>			
	REPLACE SKYLIGHT	<input type="checkbox"/>		RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>			
	BASE FLASH FAILING	<input type="checkbox"/>		NEW HATCH NEEDED	<input checked="" type="checkbox"/>			
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>						
	IMPROVE ROOF ACCESS	<input checked="" type="checkbox"/>		ADD EXTERNAL LADDER	<input type="checkbox"/>			
	REMOVE DEAD EQUIPMENT	<input checked="" type="checkbox"/>		SEAL/ COAT DUCTS	<input type="checkbox"/>			
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>		KEEP WATERWAYS CLEAN	<input type="checkbox"/>			
	SPOT REPAIR UNTIL REROOF	<input checked="" type="checkbox"/>		TRIM TREES	<input checked="" type="checkbox"/>			
	CLEAR ROOF OF DEBRIS	<input checked="" type="checkbox"/>		HVAC REPAIR NEEDED	<input checked="" type="checkbox"/>			
	HAZMAT SUSPECTED	<input type="checkbox"/>		KEEP SS GUTTERS CLEAR	<input type="checkbox"/>			
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>		YES	<input type="checkbox"/>		NO	<input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input checked="" type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 ROOF IS OVER DUE FOR REPLACEMENT. ALTHOUGH YOU MIGHT GET A COUPLE MORE YEARS OUT OF THE ROOF IT MAY FAIL AT ANY TIME.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$150,000.00

An aerial view of the building.



An overview photo from the roof level.



Dead equipment should be removed and support flashings redesigned.



The photo below shows cracked blisters near the scuppers.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	B
ROOF SQ FT	8,600

ROOF CONSTRUCTION										
ROOF AGE	2001	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input type="checkbox"/>	SCUPPERS	<input checked="" type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL SEAMS	<input type="checkbox"/>	RIDGING/BLISTERS	<input type="checkbox"/>	SS RATING
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input checked="" type="checkbox"/>	BRITTLE MEMBRANE	<input checked="" type="checkbox"/>	
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input checked="" type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	COUNTERFLASH NEEDED	<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
	BASE FLASH FAILING	<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input checked="" type="checkbox"/>	SEAL/ COAT DUCTS	<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input checked="" type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO <input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 ROOF IS AGING WELL. MAY LIVE FOR ANOTHER FIVE YEARS WITH MANAGEMENT.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$129,000.00

An aerial view of the building.



An overview photo from the roof level.



The photo below shows how the small scuppers are inadequate.



The photo below shows that the base flashing is aging with craze cracking.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	C and D
ROOF SQ FT	22,000

ROOF CONSTRUCTION										
ROOF AGE	2002	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input type="checkbox"/>	SCUPPERS	<input checked="" type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>


ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL SEAMS	<input type="checkbox"/>	RIDGING/BLISTERS	<input type="checkbox"/>	SS RATING
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input checked="" type="checkbox"/>	BRITTLE MEMBRANE	<input checked="" type="checkbox"/>	
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	7
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	COUNTERFLASH NEEDED	<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input checked="" type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
	BASE FLASH FAILING	<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input checked="" type="checkbox"/>	SEAL/ COAT DUCTS	<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input checked="" type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO <input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 ROOF IS IN FAIR CONDITION. ROOF MAY LAST FIVE PLUS YEARS IF MANAGED.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$330,000.00

An aerial view of the building.



An overview photo from the roof level.



The photo below shows debris that can be removed from the roof.



The photo below shows craze cracking - and an undersized scupper drainage system.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	Gardeners Shed
ROOF SQ FT	314

ROOF CONSTRUCTION										
ROOF AGE	UNKNOWN	<input type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input checked="" type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	SHINGLE	<input checked="" type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	BUR JOSAM	<input type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input checked="" type="checkbox"/>	OVER EDGE	<input checked="" type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input checked="" type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	RESEAL SEAMS	<input type="checkbox"/>	BLISTERS and/or RIDGING	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>	
	HEAVY WEAR	<input type="checkbox"/>	BROKEN TILES - 10-20	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	8
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	PERIMETER DAMAGE	<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	-
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>		<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO <input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input checked="" type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 ROOF LOOKS ALRIGHT.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$250.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$4,710.00

An aerial view of the building.



An overview photo from the ground level.



The photo below shows dryrot of the deck at the roof perimeter eaves.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	E
ROOF SQ FT	11,400

ROOF CONSTRUCTION										
ROOF AGE	2001	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input checked="" type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#	
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4	
	RESEAL SEAMS	<input type="checkbox"/>	RIDGING/BLISTERS	<input checked="" type="checkbox"/>	SS RATING	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>		
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>		
	CRAZE CRACKING	<input checked="" type="checkbox"/>	BRITTLE MEMBRANE	<input checked="" type="checkbox"/>		
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>		
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5	
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>		
	SOME PONDING	<input checked="" type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>		
		<input type="checkbox"/>		<input type="checkbox"/>		
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5	
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING	
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>		
	RESEAL WALL FLASHING	<input type="checkbox"/>	COUNTERFLASH NEEDED	<input type="checkbox"/>		
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4	
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input checked="" type="checkbox"/>		
	CLEAR DRAINS	<input checked="" type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>		
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>		
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	3	
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>		
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>		
	BASE FLASH FAILING	<input type="checkbox"/>		<input type="checkbox"/>		
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>				
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>		
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>	SEAL/ COAT DUCTS	<input type="checkbox"/>		
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>		
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>		
	CLEAR ROOF OF DEBRIS	<input checked="" type="checkbox"/>	HVAC REPAIR NEEDED	<input checked="" type="checkbox"/>		
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>		
LEAKS	EVIDENCE OF LEAKS	<input checked="" type="checkbox"/>	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 ROOF IS IN FAIR CONDITION. ROOF IS TOO CLOSE TO END OF LIFE TO WARRANT SYSTEM WIDE REPAIRS - SPOT REPAIR UNTIL REPLACED. CLOSER TO THREE YEARS OR LESS ON THIS ROOF REPLACEMENT.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINTENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$171,000.00

An aerial view of the building.



An overview photo from the roof level.



The photo below shows a giant blister - these roofs have many blisters.



The photo below shows repairs which is evidence of leaking.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	Front Canopy
ROOF SQ FT	2,000

ROOF CONSTRUCTION										
ROOF AGE	UNKNOWN	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input checked="" type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input checked="" type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	7
	RESEAL SEAMS	<input type="checkbox"/>	RIDGING/BLISTERS	<input type="checkbox"/>	SS RATING
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>	
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	7
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	7
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	COUNTERFLASH NEEDED	<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	7
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	-
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
	BASE FLASH FAILING	<input type="checkbox"/>	NEW HATCH NEEDED	<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>	SEAL/ COAT DUCTS	<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO <input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input checked="" type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
THIS ROOF LOOK GOOD.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$30,000.00



BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	Gardeners Shed
ROOF SQ FT	680

ROOF CONSTRUCTION										
ROOF AGE	UNKNOWN	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	SHINGLE	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	BUR JOSAM	<input type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input checked="" type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input checked="" type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS				#		
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4	
	RESEAL SEAMS	<input type="checkbox"/>	BLISTERS and/or RIDGING	<input checked="" type="checkbox"/>		
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>		
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>		
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>		
	HEAVY WEAR	<input type="checkbox"/>	BROKEN TILES - 10-20	<input type="checkbox"/>		
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	8	
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>		
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>		
		<input type="checkbox"/>		<input type="checkbox"/>		
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	2	
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>		
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>		
	RESEAL WALL FLASHING	<input type="checkbox"/>	PERIMETER FASCIA DAMAGE	<input checked="" type="checkbox"/>		
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4	
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>		
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>		
	GUTTER REPAIR NEEDED	<input checked="" type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>		
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	-	
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>		
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>		
		<input type="checkbox"/>		<input type="checkbox"/>		
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>				
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>		
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>		<input type="checkbox"/>		
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>		
	SPOT REPAIR UNTIL REROOF	<input checked="" type="checkbox"/>	TRIM TREES	<input type="checkbox"/>		
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>		
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP GUTTERS CLEAR	<input type="checkbox"/>		
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING			
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY	<input checked="" type="checkbox"/>	
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY	<input type="checkbox"/>	
FAIR	REPLACE OR COAT IN 3-5 YEARS	<input type="checkbox"/>	
MARGINAL	REPLACE OR COAT IN 5-10 YEARS	<input type="checkbox"/>	
GOOD	REPLACE OR COAT IN 10-15 YEARS	<input type="checkbox"/>	
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD	<input type="checkbox"/>	

ADDITIONAL NOTES
 THE EXISTING ROOF WAS NOT INSTALLED PROFESSIONALLY - IT IS SIMPLY A CAP SHEET ROLLED OUT AND NAILED TO THE DECK. IT IS RECOMMENDED THAT THIS ROOF BE ADDED TO THE NEXT LARGE ROOF REPLACEMENT PROJECT IN ORDER TO SAVE MONEY.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$250.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$10,200.00

An aerial view of the building.



An overview photo from the ground level.



The photo below shows dryrot of the deck at the roof perimeter eaves and gutter damage.



The photo below shows the membrane nailed down from the top.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	H
ROOF SQ FT	15,000

ROOF CONSTRUCTION										
ROOF AGE	2001	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input checked="" type="checkbox"/>	PLYWOOD	<input type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input checked="" type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input checked="" type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input checked="" type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	SS 2:12	<input checked="" type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4
	RESEAL SEAMS	<input type="checkbox"/>	RIDGING/BLISTERS	<input type="checkbox"/>	SS RATING
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input checked="" type="checkbox"/>	BRITTLE MEMBRANE	<input checked="" type="checkbox"/>	
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input checked="" type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	COUNTERFLASH NEEDED	<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
	BASE FLASH FAILING	<input type="checkbox"/>	NEW HATCH NEEDED	<input checked="" type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input checked="" type="checkbox"/>	SEAL/ COAT DUCTS	<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input checked="" type="checkbox"/>	TRIM TREES	<input checked="" type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input checked="" type="checkbox"/>	HVAC REPAIR NEEDED	<input checked="" type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO
					<input checked="" type="checkbox"/>


ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES

ROOF IS OVER DUE FOR REPLACEMENT IN APPROXIMATELY THREE YEARS. ON THE METAL ROOF, FASTENERS SHOULD BE TIGHTENED AND/OR SEALED AND THE TROUGH NEEDS TO BE CLEARED.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$225,000.00

An aerial view of the building.



An overview photo from the roof level.



AC unit is draining directly onto the roof.



The photo below shows ponding and drainage issues.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	I, J, and K
ROOF SQ FT	19,000

ROOF CONSTRUCTION										
ROOF AGE	1997	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input type="checkbox"/>	ISO	<input checked="" type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input checked="" type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input type="checkbox"/>	SCUPPERS	<input checked="" type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>


ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS				#		
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	3	
	RESEAL SEAMS	<input type="checkbox"/>	RIDGING/BLISTERS	<input checked="" type="checkbox"/>	SS RATING	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>		
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>		
	CRAZE CRACKING	<input checked="" type="checkbox"/>	VERY BRITTLE MEMBRANE	<input checked="" type="checkbox"/>		
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>		
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4	
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>		
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input checked="" type="checkbox"/>		
		<input type="checkbox"/>		<input type="checkbox"/>		
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	3	
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING	
	RESEAL/RECOAT AC DUCT	<input checked="" type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>		
	RESEAL WALL FLASHING	<input type="checkbox"/>	COUNTERFLASH NEEDED	<input type="checkbox"/>		
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4	
	ADD/ENHANCE CRICKETS	<input checked="" type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input checked="" type="checkbox"/>		
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>		
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>		
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4	
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>		
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>		
	BASE FLASH FAILING	<input type="checkbox"/>	NEW HATCH NEEDED	<input checked="" type="checkbox"/>		
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>				
	IMPROVE ROOF ACCESS	<input checked="" type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>		
	REMOVE DEAD EQUIPMENT	<input checked="" type="checkbox"/>	SEAL/ COAT DUCTS	<input type="checkbox"/>		
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>		
	SPOT REPAIR UNTIL REROOF	<input checked="" type="checkbox"/>	TRIM TREES	<input checked="" type="checkbox"/>		
	CLEAR ROOF OF DEBRIS	<input checked="" type="checkbox"/>	HVAC REPAIR NEEDED	<input checked="" type="checkbox"/>		
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>		
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING			
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY	<input type="checkbox"/>	
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY	<input checked="" type="checkbox"/>	
FAIR	REPLACE OR COAT IN 3-5 YEARS	<input type="checkbox"/>	
MARGINAL	REPLACE OR COAT IN 5-10 YEARS	<input type="checkbox"/>	
GOOD	REPLACE OR COAT IN 10-15 YEARS	<input type="checkbox"/>	
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD	<input type="checkbox"/>	

ADDITIONAL NOTES
 ROOF IS OVER DUE FOR REPLACEMENT. ALTHOUGH YOU MIGHT GET A COUPLE MORE YEARS OUT OF THE ROOF IT MAY FAIL AT ANY TIME. K IS IN THE BEST SHAPE OUT OF THE THREE. K HAS RECEIVED A NEW HATCH.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$285,000.00

An aerial view of the building.



An overview photo from the roof level.



Photo below shows the need to reseal the AC ducts.



Photo below shows blisters in the field.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	L
ROOF SQ FT	9,900

ROOF CONSTRUCTION										
ROOF AGE	2002	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input type="checkbox"/>	SCUPPERS	<input checked="" type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	3
	RESEAL SEAMS	<input type="checkbox"/>	RIDGING/BLISTERS	<input type="checkbox"/>	SS RATING
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input checked="" type="checkbox"/>	
	EXCESSIVE WEAR	<input checked="" type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input checked="" type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input checked="" type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	COUNTERFLASH NEEDED	<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	ADD/ENHANCE CRICKETS	<input checked="" type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input checked="" type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
	BASE FLASH FAILING	<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input checked="" type="checkbox"/>	SEAL/ COAT DUCTS	<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input checked="" type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO <input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input checked="" type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 ROOF IS TOO OLD TO DO A SYSTEM WIDE REPAIR. SPOT REPAIR UNTIL RELACE. TWO TO THREE YEARS ON THIS ROOF FOR LIFESPAN.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$148,500.00

An aerial view of the building.



An overview photo from the roof level.



The photo below shows how the small scuppers are inadequate.



The photo below shows exposed fibers of the membrane.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	Large Canopy
ROOF SQ FT	4,400

ROOF CONSTRUCTION										
ROOF AGE	UNKNOWN	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input checked="" type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input checked="" type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS				#		
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4	
	RESEAL SEAMS	<input type="checkbox"/>	RIDGING/BLISTERS	<input type="checkbox"/>	SS RATING	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>		
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>		
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>		
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>		
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4	
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>		
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input checked="" type="checkbox"/>		
		<input type="checkbox"/>		<input type="checkbox"/>		
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4	
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING	
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>		
	RESEAL WALL FLASHING	<input type="checkbox"/>	COUNTERFLASH NEEDED	<input type="checkbox"/>		
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4	
	ADD/ENHANCE CRICKETS	<input checked="" type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input checked="" type="checkbox"/>		
	CLEAR DRAINS	<input checked="" type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>		
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>		
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	-	
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>		
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>		
	BASE FLASH FAILING	<input type="checkbox"/>	NEW HATCH NEEDED	<input type="checkbox"/>		
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>				
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>		
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>	SEAL/ COAT DUCTS	<input type="checkbox"/>		
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>		
	SPOT REPAIR UNTIL REROOF	<input checked="" type="checkbox"/>	TRIM TREES	<input type="checkbox"/>		
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>		
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>		
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 THIS ROOF IS NOT ON THE LIST. GUESSING ON THE AGE. KNOWING THE TRUE AGE WOULD SOLIDIFY THE LIFESPAN ESTIMATE.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$66,000.00

An aerial view of the building.



An overview photo from the roof level.



Photo below shows that the drains are slow causing a ponding problem.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	M
ROOF SQ FT	9,900

ROOF CONSTRUCTION										
ROOF AGE	1995	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input type="checkbox"/>	SCUPPERS	<input checked="" type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	3
	RESEAL SEAMS	<input type="checkbox"/>	RIDGING/BLISTERS	<input type="checkbox"/>	SS RATING
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input checked="" type="checkbox"/>	BRITTLE MEMBRANE	<input checked="" type="checkbox"/>	
	EXCESSIVE WEAR	<input checked="" type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input checked="" type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input checked="" type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	COUNTERFLASH NEEDED	<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	ADD/ENHANCE CRICKETS	<input checked="" type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input checked="" type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
	BASE FLASH FAILING	<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input checked="" type="checkbox"/>	SEAL/ COAT DUCTS	<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input checked="" type="checkbox"/>	HVAC REPAIR NEEDED	<input checked="" type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO
				<input checked="" type="checkbox"/>	

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input checked="" type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 ROOF IS TO OLD TO DO A SYSTEM WIDE REPAIR. SPOT REPAIR UNTIL RELACE.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$148,500.00


An aerial view of the building.



An overview photo from the roof level.



The photo below shows an AC unit leaking onto the roof close to a crack in sealant.



The photo below shows exposed fibers of the membrane.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	N
ROOF SQ FT	5,500

ROOF CONSTRUCTION										
ROOF AGE	2000	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input checked="" type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL SEAMS	<input type="checkbox"/>	REPAIR BLISTERS or RIDGING	SS RATING	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED		
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS		
	CRAZE CRACKING	<input checked="" type="checkbox"/>	BRITTLE MEMBRANE		
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED		
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION		
	SOME PONDING	<input checked="" type="checkbox"/>	EXCESSIVE PONDING		
		<input type="checkbox"/>			
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	SS RATING	
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL		
	RESEAL WALL FLASHING	<input type="checkbox"/>	COUNTERFLASH NEEDED		
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW		
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER		
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED		
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	3
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT		
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE		
	BASE FLASH FAILING	<input checked="" type="checkbox"/>			
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER		
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>	SEAL/ COAT DUCTS	<input checked="" type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input checked="" type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>	

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
NEW HATCH IS NEEDED.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$82,500.00

An aerial view of the building.



An overview photo from the roof level.



The photo below shows ponding problems.



The photo below shows the penetration base flashing failing.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	Portables N5-N12
ROOF SQ FT	9,700

ROOF CONSTRUCTION										
ROOF AGE	UNKNOWN	<input type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input checked="" type="checkbox"/>
DECK TYPE	METAL	<input checked="" type="checkbox"/>	PLYWOOD	<input type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input checked="" type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	GALVINIZED	<input checked="" type="checkbox"/>	MS CAP	<input type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input checked="" type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>


ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS								#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>					RATING	4
	RESEAL SEAMS	<input type="checkbox"/>	REPAIR BLISTERS or RIDGING	<input type="checkbox"/>				
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>				
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>				
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>				
	EXCESSIVE WEAR	<input type="checkbox"/>	SS PANEL DAMAGE	<input checked="" type="checkbox"/>				
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>					RATING	5
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>				
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>				
		<input type="checkbox"/>		<input type="checkbox"/>				
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>					RATING	5
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>				
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT EDGE FLASH	<input type="checkbox"/>				
	RESEAL WALL FLASHING	<input type="checkbox"/>	REPLACE FASTENERS	<input type="checkbox"/>				
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>					RATING	5
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>				
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>				
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>				
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>					RATING	-
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>				
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>				
		<input type="checkbox"/>		<input type="checkbox"/>				
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>						
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>				
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>		<input type="checkbox"/>				
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>				
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>				
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>				
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input checked="" type="checkbox"/>				
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>		

ROOF CONDITION - OVERALL SYSTEM RATING		
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY	<input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY	<input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS	<input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS	<input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS	<input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD	<input type="checkbox"/>

ADDITIONAL NOTES
 ROOFS ARE IN FAIR CONDITION WITH NO SIGNS OF RUST. THE PHYSICAL DAMAGE TO THE STANDING SEAM PANELS MAY RESULT IN LEAKS - MANAGE AND REPAIR/PATCH IF NECESSARY.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$500.00
ROOF RECOATING	\$97,000.00
ROOF REPLACEMENT	\$0.00

An aerial view of the building.



An overview photo from the roof level.



The photo below shows damage to the metal roof.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	O Gym, P, Q
ROOF SQ FT	31,800

ROOF CONSTRUCTION										
ROOF AGE	2003	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input checked="" type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL SEAMS	<input type="checkbox"/>	REPAIR BLISTERS or RIDGING	<input type="checkbox"/>	SS RATING
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input checked="" type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>	
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input checked="" type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>		<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4
	ADD/ENHANCE CRICKETS	<input checked="" type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input checked="" type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input checked="" type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input checked="" type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>		<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input checked="" type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO <input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
BUDGET TO REPLACE IN APPROXIMATELY FIVE YEARS.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$477,000.00

The photo below shows the need for new skylights when the roof is redone.



The photo below shows some ponding.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	Pool Treatment
ROOF SQ FT	1,000

ROOF CONSTRUCTION										
ROOF AGE	UNKNOWN	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input checked="" type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input checked="" type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>


ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL SEAMS	<input type="checkbox"/>	RIDGING/BLISTERS	<input type="checkbox"/>	SS RATING
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>	
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	COUNTERFLASH NEEDED	<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
	BASE FLASH FAILING	<input type="checkbox"/>	NEW HATCH NEEDED	<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>	SEAL/ COAT DUCTS	<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO <input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input checked="" type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 THIS ROOF IS NOT ON THE LIST. GUESSING ON THE AGE. KNOWING THE TRUE AGE WOULD SOLIDIFY THE LIFESPAN ESTIMATE.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$15,000.00

An aerial view of the building.



An overview photo of the roof.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	Press Box
ROOF SQ FT	300

ROOF CONSTRUCTION										
ROOF AGE	UNKNOWN	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	SHINGLE	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	BUR JOSAM	<input type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input checked="" type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	RESEAL SEAMS	<input type="checkbox"/>	BLISTERS and/or RIDGING	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>	
	HEAVY WEAR	<input type="checkbox"/>	BROKEN TILES - 10-20	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	PERIMETER FASCIA DAMAGE	<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	-
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>		<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>	

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 ROOF IS IN FAIR CONDITION.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$250.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$4,500.00

An aerial view of the building.



An overview photo from the ground level.



An overview photo from the roof level.



Another overview photo from the roof level.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	R Food Services
ROOF SQ FT	4,300

ROOF CONSTRUCTION										
ROOF AGE	2000	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input checked="" type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input checked="" type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input checked="" type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	RESEAL SEAMS	<input type="checkbox"/>	REPAIR BLISTERS or RIDGING	<input type="checkbox"/>	SS RATING
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>	
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input checked="" type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	3
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	COUNTERFLASH NEEDED	<input checked="" type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input checked="" type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>	SEAL/ COAT DUCTS	<input checked="" type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input checked="" type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO <input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
NEW HATCH IS NEEDED.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$64,500.00

An aerial view of the building.



An overview photo from the roof level.



The photo below shows AC ducts in need of being resealed.



The photo below shows the edge detail without an appropriate counterflashing.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	S Admin and Career Center
ROOF SQ FT	7,200

ROOF CONSTRUCTION										
ROOF AGE	2004	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input checked="" type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>


ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL SEAMS	<input type="checkbox"/>	REPAIR BLISTERS or RIDGING	<input type="checkbox"/>	SS RATING
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>	
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	3
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input checked="" type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>		<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input checked="" type="checkbox"/>		RATING	3
	RESEAL/REPAIR ALL	<input checked="" type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input checked="" type="checkbox"/>		<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO
				<input type="checkbox"/>	

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$108,000.00

An aerial view of the building.



An overview photo from the roof level.



The photo below shows penetrations in need of repair.



The photo below shows excessive ponding.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	Gardeners Shed
ROOF SQ FT	900

ROOF CONSTRUCTION										
ROOF AGE	UNKNOWN	<input type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input checked="" type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	SHINGLE	<input checked="" type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	BUR JOSAM	<input type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input checked="" type="checkbox"/>	OVER EDGE	<input checked="" type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input checked="" type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4
	RESEAL SEAMS	<input type="checkbox"/>	BLISTERS and/or RIDGING	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>	
	HEAVY WEAR	<input checked="" type="checkbox"/>	BROKEN TILES - 10-20	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	8
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	2
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	PERIMETER DAMAGE	<input checked="" type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	-
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>		<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input checked="" type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO
				<input checked="" type="checkbox"/>	

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input checked="" type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 ROOF PERIMETER EVES PLYWOOD DECK IS FALLING APART WITH DRYROT. THIS IS NOT AFFECTING THE BUILDING WITH LEAKS.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$250.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$13,500.00

An aerial view of the building.



An overview photo from the roof level.



The photo below shows dryrot of the deck at the roof perimeter eaves.



Another overview photo.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	T
ROOF SQ FT	5,700

ROOF CONSTRUCTION										
ROOF AGE	2000	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input checked="" type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL SEAMS	<input type="checkbox"/>	RIDGING	<input checked="" type="checkbox"/>	SS RATING
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input checked="" type="checkbox"/>	BRITTLE MEMBRANE	<input checked="" type="checkbox"/>	
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input checked="" type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input checked="" type="checkbox"/>		RATING	3
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input checked="" type="checkbox"/>	
	RESEAL WALL FLASHING	<input checked="" type="checkbox"/>	COUNTERFLASH NEEDED	<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	3
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
	BASE FLASH FAILING	<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input checked="" type="checkbox"/>	SEAL/ COAT DUCTS	<input checked="" type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input checked="" type="checkbox"/>	HVAC REPAIR NEEDED	<input checked="" type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO
				<input checked="" type="checkbox"/>	

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 ROOF IS IN FAIR CONDITION. CLOSER TO THREE YEARS ON THIS ROOF REPLACEMENT.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$4,000.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$85,500.00

An aerial view of the building.



An overview photo from the roof level.



The photo below shows that the walls need repair and coating.



The photo below shows equipment that should be covered or removed.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	Portables T10 and T11
ROOF SQ FT	2,200

ROOF CONSTRUCTION										
ROOF AGE	UNKNOWN	<input type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input checked="" type="checkbox"/>
DECK TYPE	METAL	<input checked="" type="checkbox"/>	PLYWOOD	<input type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input checked="" type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	GALVINIZED	<input checked="" type="checkbox"/>	MS CAP	<input type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input checked="" type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>


ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	4
	RESEAL SEAMS	<input type="checkbox"/>	REPAIR BLISTERS or RIDGING	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>	
	EXCESSIVE WEAR	<input type="checkbox"/>	SIGNIFICANT RUST	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT EDGE FLASH	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	REPLACE FASTENERS	<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	-
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>		<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input checked="" type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input checked="" type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO
				<input checked="" type="checkbox"/>	

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 ROOFS ARE IN FAIR CONDITION WITH NO SIGNS OF RUST.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$500.00
ROOF RECOATING	\$22,000.00
ROOF REPLACEMENT	\$0.00

An aerial view of the building.



An overview photo from the roof level.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	U
ROOF SQ FT	9,000

ROOF CONSTRUCTION										
ROOF AGE	2007	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	COATING	<input checked="" type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input checked="" type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input checked="" type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	RESEAL SEAMS	<input type="checkbox"/>	RIDGING/BLISTERS	<input checked="" type="checkbox"/>	SS RATING
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>	
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	8
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input checked="" type="checkbox"/>		RATING	6
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	RESEAL CAP SEAMS	<input checked="" type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	6
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	8
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
	BASE FLASH FAILING	<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>	SEAL/ COAT DUCTS	<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input checked="" type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO <input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input checked="" type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 ROOF IS IN MARGINAL CONDITION. RESEAL THE CAPS AND CLEAR THE GUTTERS.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$0.00
ROOF REPLACEMENT	\$135,000.00

An aerial view of the building.



An overview photo from the roof level.



The photo below shows that it's time to reseal the cap flashing seams.



Somehow the gutters need to be cleared periodically for this tall building.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	Portables V1 and V2
ROOF SQ FT	2,200

ROOF CONSTRUCTION										
ROOF AGE	UNKNOWN	<input type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input checked="" type="checkbox"/>
DECK TYPE	METAL	<input checked="" type="checkbox"/>	PLYWOOD	<input type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input checked="" type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input checked="" type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input type="checkbox"/>
MEM SURFACE	GALVINIZED	<input checked="" type="checkbox"/>	MS CAP	<input type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input checked="" type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL SEAMS	<input type="checkbox"/>	REPAIR BLISTERS or RIDGING	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>	
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>	
	CRAZE CRACKING	<input type="checkbox"/>	BRITTLE MEMBRANE	<input type="checkbox"/>	
	EXCESSIVE WEAR	<input type="checkbox"/>	SS PANEL DAMAGE	<input type="checkbox"/>	
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>	
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT EDGE FLASH	<input type="checkbox"/>	
	RESEAL WALL FLASHING	<input type="checkbox"/>	REPLACE FASTENERS	<input type="checkbox"/>	
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	5
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>	
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>	
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>	
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	-
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>	
		<input type="checkbox"/>		<input type="checkbox"/>	
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>			
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>	
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>		<input type="checkbox"/>	
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>	
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>	
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>	
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input checked="" type="checkbox"/>	
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO <input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input checked="" type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input type="checkbox"/>

ADDITIONAL NOTES
 ROOFS ARE IN FAIR CONDITION WITH NO SIGNS OF RUST.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$500.00
ROOF RECOATING	\$22,000.00
ROOF REPLACEMENT	\$0.00

An aerial view of the building.



An overview photo from the roof level.



Another overview photo.





BUILDING INFORMATION	
FACILITY	Silver Creek HS
DATE	October 21, 2014
BUILDING	X Theater
ROOF SQ FT	2,000

ROOF CONSTRUCTION										
ROOF AGE	2012	<input checked="" type="checkbox"/>	0-5 YEARS	<input type="checkbox"/>	5-10 YEARS	<input type="checkbox"/>	10-15 YEARS	<input type="checkbox"/>	15+ YEARS	<input type="checkbox"/>
DECK TYPE	METAL	<input type="checkbox"/>	PLYWOOD	<input checked="" type="checkbox"/>	PLANK	<input type="checkbox"/>	CONCRETE	<input type="checkbox"/>	LW CONCRETE	<input type="checkbox"/>
INSULATION	NONE	<input type="checkbox"/>	ISO	<input type="checkbox"/>	FIBER	<input type="checkbox"/>	PERLITE	<input type="checkbox"/>	STYRO	<input type="checkbox"/>
INSUL THICK	1 INCH	<input type="checkbox"/>	2 INCH	<input type="checkbox"/>	3 INCH	<input type="checkbox"/>	4 INCH	<input type="checkbox"/>	TAPERED	<input type="checkbox"/>
MEMBRANE	METAL SS	<input checked="" type="checkbox"/>	SINGLE PLY	<input type="checkbox"/>	BUR	<input checked="" type="checkbox"/>	MOD BIT	<input type="checkbox"/>	TWO SYSTEMS	<input checked="" type="checkbox"/>
MEM SURFACE	COATING	<input type="checkbox"/>	MS CAP	<input checked="" type="checkbox"/>	GRAVEL	<input type="checkbox"/>	SMOOTH	<input type="checkbox"/>	GRANULE	<input type="checkbox"/>
FLASHINGS	CAPSHEET	<input checked="" type="checkbox"/>	HYPALON	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
DRAINAGE	JOSAM	<input checked="" type="checkbox"/>	SCUPPERS	<input type="checkbox"/>	GUTTERS	<input checked="" type="checkbox"/>	OVER EDGE	<input type="checkbox"/>		<input type="checkbox"/>
SLOPE	SLIGHT	<input checked="" type="checkbox"/>	1:12	<input type="checkbox"/>	2:12	<input type="checkbox"/>	3:12	<input type="checkbox"/>	6:12	<input type="checkbox"/>

ROOF CONDITION - RATINGS (1-10) and RECOMMENDATIONS					#	
FIELD	REPAIRS NEEDED	<input type="checkbox"/>		RATING	8	
	RESEAL SEAMS	<input type="checkbox"/>	RIDGING/BLISTERS	<input type="checkbox"/>	SS RATING	8
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	DECK REPAIR NEEDED	<input type="checkbox"/>		
	DECK REPAIR SUSPECTED	<input type="checkbox"/>	RESEAL/RPLACE FASTENERS	<input type="checkbox"/>		
	CRAZE CRACKING	<input type="checkbox"/>	VERY BRITTLE MEMBRANE	<input type="checkbox"/>		
	EXCESSIVE WEAR	<input type="checkbox"/>	MEMBRANE FIBERS EXPOSED	<input type="checkbox"/>		
PITCH/POND	REPAIRS NEEDED	<input type="checkbox"/>		RATING	8	
	FILL PONDING AREAS	<input type="checkbox"/>	FIX DECK DEFLECTION	<input type="checkbox"/>		
	SOME PONDING	<input type="checkbox"/>	EXCESSIVE PONDING	<input type="checkbox"/>		
		<input type="checkbox"/>		<input type="checkbox"/>		
FLASHING	REPAIRS NEEDED	<input type="checkbox"/>		RATING	8	
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>	SS RATING	8
	RESEAL/RECOAT AC DUCT	<input type="checkbox"/>	RESEAL/RECOAT WALL	<input type="checkbox"/>		
	RESEAL WALL FLASHING	<input type="checkbox"/>	COUNTERFLASH NEEDED	<input type="checkbox"/>		
DRAINAGE	REPAIRS NEEDED	<input type="checkbox"/>		RATING	8	
	ADD/ENHANCE CRICKETS	<input type="checkbox"/>	ADD/ENHANCE OVERFLOW	<input type="checkbox"/>		
	CLEAR DRAINS	<input type="checkbox"/>	ADD GUTTER	<input type="checkbox"/>		
	GUTTER REPAIR NEEDED	<input type="checkbox"/>	GUTTER COATING NEEDED	<input type="checkbox"/>		
PENETRATION	REPAIRS NEEDED	<input type="checkbox"/>		RATING	8	
	RESEAL/REPAIR ALL	<input type="checkbox"/>	RESEAL/REPAIR SELECT	<input type="checkbox"/>		
	REPLACE SKYLIGHT	<input type="checkbox"/>	RAISE HEIGHT WHEN POSSIBLE	<input type="checkbox"/>		
	BASE FLASH FAILING	<input type="checkbox"/>	NEW HATCH NEEDED	<input type="checkbox"/>		
ADDITIONAL	ACTION NEEDED	<input type="checkbox"/>				
	IMPROVE ROOF ACCESS	<input type="checkbox"/>	ADD EXTERNAL LADDER	<input type="checkbox"/>		
	REMOVE DEAD EQUIPMENT	<input type="checkbox"/>	SEAL/ COAT DUCTS	<input type="checkbox"/>		
MAINTENANCE	KEEP DRAINS CLEAN	<input type="checkbox"/>	KEEP WATERWAYS CLEAN	<input type="checkbox"/>		
	SPOT REPAIR UNTIL REROOF	<input type="checkbox"/>	TRIM TREES	<input type="checkbox"/>		
	CLEAR ROOF OF DEBRIS	<input type="checkbox"/>	HVAC REPAIR NEEDED	<input type="checkbox"/>		
	HAZMAT SUSPECTED	<input type="checkbox"/>	KEEP SS GUTTERS CLEAR	<input checked="" type="checkbox"/>		
LEAKS	EVIDENCE OF LEAKS	<input type="checkbox"/>	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>

ROOF CONDITION - OVERALL SYSTEM RATING	
VERY POOR	REPLACE OR COAT IMMEDIATELY - SPOT REPAIRS ONLY <input type="checkbox"/>
POOR	REPLACE OR COAT IN 1-2 YEARS - SPOT REPAIRS ONLY <input type="checkbox"/>
FAIR	REPLACE OR COAT IN 3-5 YEARS <input type="checkbox"/>
MARGINAL	REPLACE OR COAT IN 5-10 YEARS <input type="checkbox"/>
GOOD	REPLACE OR COAT IN 10-15 YEARS <input type="checkbox"/>
EXCELLENT	ONLY IF ROOF IS LESS THAN 5 YEARS OLD <input checked="" type="checkbox"/>

ADDITIONAL NOTES
 ROOF IS NEW. METAL SS SECTION IS APPROXIMATELY 12,000SF.

BUDGET ESTIMATES	
IMMEDIATE REPAIRS AS RECOMMENDED	\$0.00
YEARLY PREVENTIVE MAINENANCE	\$1,500.00
ROOF RECOATING	\$120,000.00
ROOF REPLACEMENT	\$30,000.00

An aerial view of the building.



An overview photo from the roof level.



Keep gutters clean and clear.



If managed the metal roof should last decades.

